Stantec Analytical Validation Checklist

- Currer Funding	110 001011101111020
Project Name: Amtrak North Yard	Project Number: 213402048
Validator: Jim Tezak	Laboratory: Eurofins/Lancaster Laboratory
Date Validated: 11/21/2018	Laboratory Project Number: 1814584
Sample Start-End Date: 6/15/2017	Laboratory Report Date: 7/22/2017

Report No. ATG25

Parameters Validated:

Polychlorinated biphenyls (PCBs) by EPA SW-846 3550B/8082A - solid matrix

Percent Solids by SM 2540 G

Samples Validated (all Grab Soil):

D-5(0.0-0.3), LLI # 9054618

D-5(0.5-0.8), LLI # 9054619

D-5(1.0-1.3), LLI # 9054620

D-5(1.5-1.8), LLI # 9054621

D-5(2.0-2.3), LLI # 9054622

D-5(2.5-2.8), LLI # 9054623

D-5(3.0-3.3), LLI # 9054624

D-5(3.5-3.8), LLI # 9054625

D-5(4.0-4.3), LLI # 9054626

D-5(4.5-4.8), LLI # 9054627

D-3(4.3-4.6), LLI # 9034021

D-5(5.0-5.3), LLI # 9054628

D-5(5.5-5.8), LLI # 9054629

D-5(6.0-6.3), LLI # 9054630

DUP-25, LLI # 9054631

D-5(6.5-6.8), LLI # 9054632

D-5(6.5-6.8)MS, LLI # 9054633

D-5(6.5-6.8)MSD, LLI # 9054634

A-6(0.0-0.3), LLI # 9054635

A-6(0.5-0.8), LLI # 9054636

A-6(1.0-1.3), LLI # 9054637

VALIDATION CRITERIA CHECK

Validation Flags Applicable to this Review:

- **U** The analyte was analyzed for, but not detected above the reported sample quantitation limit.
- **J** The analyte was positively identified; the associated numerical value is the approximate concentration of the analyte in the sample.
- **J+** Result is estimated quantity but the result may be biased high.
- **J-** Result is estimated quantity but the result may be biased low.
- **UJ** The analyte was not detected above the reported sample quantitation limit. However, the reported quantitation limit is approximate and may or may not represent the actual limit of quantitation necessary to accurately and precisely measure the analyte in the sample.
- **NJ** The analysis indicates the presence of an analyte that has been "tentatively identified" and the associated numerical value represents its approximate concentration.
- **B** The analyte was detected in the method, field, and/or trip blank.
- **R** The sample results are rejected due to serious deficiencies in the ability to analyze the sample and meet quality control criteria. The presence or absence of the analyte cannot be verified.

1.	Were all the analyses requested for the samples submitted with each COC completed by the lab?		Yes X	No			
Con	Comments:						
2.	Did the laboratory identify any non-conformances related to the analytical result?		Yes	No X			
Comments:							
3.	3. Were sample Chain-of-Custody forms complete?		Yes X	No			
Con	nments:						
San	nples were listed on two chains-of-custody (COCs), COC #'s	534140 and 5	534139.				
4.	4. Were samples received in good condition and at the appropriate temperature?		Yes X	No			
Comments: The laboratory noted on the Sample Administration Receipt Documentation Log that the shipping container was not sealed and there was no custody seal present when the samples were received.							
5.	Were sample holding times met?		Yes X	No			
Comments:							
6.	Were correct concentration units reported?		Yes X	No			
Con	nments:						
Res	ults for all soil samples were reported in units of milligrams p	oer kilogram (n	ng/kg).				
7.	Were detections found in laboratory blank samples?		Yes	No X			
Con	nments:						
8. blan	Were detections found in field blank, equipment rinse k, and/or trip blank samples?	NA X	Yes	No			
	Comments: No field blanks were submitted in this sample delivery group (SDG).						
9.	Were instrument calibrations within method criteria?	NA X	Yes	No			
	nments:						
Not	Applicable, Level 2 data validation.						
10.	Were surrogate recoveries within control limits?		Yes X	No			
Comments:							

11. Were laboratory control sample(s) (LCS/LCSD) sample recoveries within control limits?		Yes X	No
Comments:			
12. Were matrix spike (MS/MSD) recoveries within control limits?	NA	Yes X	No
Comments:			
The sample D-5(6.5-6.8) was analyzed as the site-specific MS/171990001A. The sample D-8(3.5-3.8) from SDG ATG24 was soil samples in batch 171980036A. All percent recoveries (%R	analyzed as the	e site-specific N	IS/MSD for
13. Were RPDs within control limits?		Yes X	No
Comments:			
14. Were dilutions required on any samples?		Yes X	No
Comments:			
Three soil samples required dilution prior to analysis, with dilution Sample reporting limits were adjusted accordingly. No data we		ing from 10X to	500X.
15. Were Tentatively Identified Compounds (TIC) present?	NA X	Yes	No
Comments: TIC not requested.			
16. Were organic system performance criteria met?	NA X	Yes	No
Comments:			
Not Applicable, Level II data validation.			
17. Were GC/MS internal standards within method criteria?	NA X	Yes	No
Comments: Not Applicable, Level II data validation.			
18. Were inorganic system performance criteria met?	NA	Yes X	No
Comments:			
19. Were blind field duplicates collected? If so, discuss the precision (RPD) of the results.		Yes X	No
Duplicate Sample ID Primary Sample No	<u>).</u>		
DUP-25 D-5(6.0-6.3)			
Comments: No PCB Aroclors were detected in either sample.			

20. Were at least 10 percent of the hard copy results compared to the Electronic Data Deliverable Results?				No	Initials KEF			
Comments:	Comments:							
21. Other?				Yes	No X			
Comments: All samples were validated according to the USEPA 2014 NFGs and DNREC SOPCAP. All data are considered usable as qualified. No data have been rejected.								
PRECISION, ACCURACY, METHOD COMPLIANCE AND COMPLETENESS ASSESSMENT								
Precision:	Acceptable X	Unaccepta	able	Initials JET				
Comments:								
Sensitivity:	Acceptable X	Unaccepta	able	Initials JET				
Comments:								
Accuracy:	Acceptable X	Unaccepta	able	Initials JET				
Comments:								
Representativeness:	Acceptable X	Unaccepta	able	Initials JET				
Comments:								
Method Compliance:	Acceptable X	Unaccepta	able	Initials JET				
Comments:								
Completeness:	Acceptable X	Unaccepta	able	Initials JET				
Comments:								